

**Errata – Strut-and-tie Models**

**Published Dec 2014**

**CCIP-057**

Page 9

A double asterisk is missing from one of the paragraphs of text. Please see below for where this '\*\*' should appear

*“The angle between the struts and ties should be large enough to avoid strain incompatibilities, i.e. large enough to avoid ties extending and struts shortening in almost the same direction. The minimum angle between struts and ties should not be taken as less than 35° \*\*.”*